



2900 Selma Highway  
Montgomery, AL 36108 USA  
Tel: 334-386-5400 Fax: 334-386-5450

# Service Bulletin

Bulletin No. 020

Issue Date: October 17, 2001

**TO:** All Distributors, FBO's, Repair Stations, and owners of effected Part Numbered and Serial Numbered Turbochargers.

**SUBJECT:** 406610-9005 (Cessna P/N: C295001-0101) Turbochargers with missing anti-rotation pins.

**MODELS AFFECTED:** Only those RAJAY (formally GARRETT) Model TEO659 Turbochargers found to have the following Serial Numbers:

AAO08336	CDN00033	HBO111	LAR0264	QGO105L	VL-L0133
ABO12678	CDN00064	HFR0222	LB0151	LKR0129	WA-L0106
ABO30535	CDN00380	HGO138	LFA017	QIR0201	WC-L0113
ACO33185	CEN00016	HJO102	LKR0129	QIR0215	WJL0154
ADO27907	CEN00017	HKR0261	LLR0169	RAP0133	WKL0115
AHO03678	CFO154	IBO195	ML0121	RBO159L	WL-L0141
AJO21344	CFR0226	ICO229	MLR0244	RCO21233	XAO00047
AJO21349	CGO185	ICO258	NAB021985	RCR0106	XHO28391
AKO18452	CKO128	IDR0398	NAO133	RIR0156	XHO28403
AKO18469	CKR0208	IFO245	NCO101	RJO15543	XKO16898
AKO18470	CLL18645	IGR0316	NCR0387	RLR0303	XLL15565
ALO01870	DAN00333	IJR0142	NFO102	RLR0396	XLO19379
BAO15613	DAR0131	ILR053	NHR0194	SDR0128	XLO35966
BAO23728	DBN00038	JAO190	NLR0195	SDR3678	YAO00474
BCO26627	DER0133	JBR0153	NLR0212	SER0125	YCO01304
BCO58706	DFN00033	JD0156	NLR0229	SIR0278	YFO33248
BFO25044	DIO146	JIR0282	OCR207	TGR0161	YHO07951
BFO36918	EDR0271	JLO175	OER0504	TKR0145	YKO15218
BGO33350	FA0124	JLR0156	OFR0611	UAR0119	YKO33375
BHO19418	FDO0140	KBO101	PCR0147	UAR0120	YKO33431
BHO48141	FFR0289	KBR0245	PER0109	UBR0250	ZAO30056
BJO25438	FG0136	KCR0112	PER0112	UCR0123	ZCO24251
BKO02931	FO115L	KE0102	PER0155	UGR7118	ZCO26131
BKO33087	FRO186	KEO116	PER0252	UIR0142P	ZDO12917
BLN27495	GAO106	KFR0358	PER0262	UIR0181P	ZFO22050
CBN00278	GBR0229	KFR0385	PGO130	VCL0101	ZHO24361
CBN00296	GCO153	KHR0174	PGR0110	VD-L0111	ZIO31085
CCN00207	GER0291	KHR0176	PIO128	VDR7669	ZIO33469
CCN00438	GHR0127	KJR0183	PLR0168	VF-L0114	ZKO01740
CCN00983	GJR0925	KJR0218	QBR0257	VG-L0120	ZKO07357
CCN0973	GKO141	LAR0232	QCR0162	VH-L0148	ZKO1745

**TIME OF COMPLIANCE:** At the next scheduled inspection but not to exceed 25 hours of operation.

## **All Distributors, FBO's, and Repair Stations are requested to:**

Immediately examine your stock and records for the time period of October, 2000 thru September, 2001 for any 406610-9005 turbochargers with the aforementioned Serial Numbers. Existing shelf-stocked units must immediately be returned to the factory. Any unit currently installed on an aircraft must be returned to the factory within, but not exceeding, twenty-five hours of operation. Each returned unit will be inspected to verify the installation of the Anti-Rotation Pin P/N: 400705-0000.

Identify which customers have purchased these turbochargers in the time frame specified. It is imperative that you require your customers to return any Turbocharger bearing one of the suspect Serial Numbers to Consolidated Fuel Systems, ATTN. Jacob Harper, Product Retrieval.

Remove the turbocharger(s) and call the Hartzell Engine Technologies Customer Care Center or Consolidated Fuel Systems to receive an Returned Material Authorization (RMA) Number. The RMA number will help to expedite the processing of your unit. Returned units must have the RMA number plainly affixed to the turbocharger itself.

Units returned to the factory for authorized repairs will receive immediate and prompt attention. HET or CFS will exercise a priority turn-around of all subject turbochargers. These turbochargers will be returned as time-continued units and will retain their original warranty agreement.

### **Consolidated Fuel Systems, Inc**

1400 East South Blvd.  
Montgomery, AL. 36116  
(800)-334-6359

### **Hartzell Engine Technologies Customer Care Center**

2900 Selma Highway  
Montgomery, AL 36108 USA  
(877)-359-5355