

Twin Cessnas Affected by South Wind AD 2017-06-03

Aircraft Make	Aircraft Model(s)	South Wind Part Number	Janitrol Aero Part Number	Approval Basis PMA / STC
Cessna	310, A S/N 35000 thru 35546	940	CD14010K3	STC SA00971CH
Cessna	310A, S/N 35547 and up, 310B, 310C, 310D, 310E, 310F, 310G, 310H, E310H, 320, 320-1, 320A, 320B	8240A, 8240C, 8253B	CD12065-1	PMA
Cessna	310Q, S/N 310Q-0454 and up, T310Q, S/N T310Q-0454 and up	8240E	CD12064-1	PMA
Cessna	310R, S/N 310R-0001 thru 310R-0800, T310R, S/N T310R-0001 thru T310R-0800	8259HR2	CD14072-1	PMA
Cessna	310R, S/N 310R-0801 and up, T310R, S/N T310R-0801 and up	8259JR2	CD14073-1	PMA
Cessna	335	8259M	CD14075-1	PMA
Cessna	340, 340A, S/N 340A-0001 thru 340A-0200.	8472D	CD14077-1	PMA
Cessna	401, 401A, 401B, 402, 402A, 402B, 402C, 404	8259GL, 8259GL1, 8259GL2, 8259HL1, 8259HL2	CD14071-1	PMA
Cessna	411, 411A	8259A, 8259DL, 8259FL, 8259FL1	CD14066-1	PMA
Cessna	414, S/N 414-0262 thru 414-0900	8472C, 8472E	CD14078-1	PMA
Cessna	421B, S/N 421B-229 and up, 421C, S/N 421C-0001 thru 421C-0200	8472C, 8472E	CD14078-1	PMA

